

To

The Principal,
Doon International School,
Verka Byepass, Amritsar.

No. 39

Dated:- 04/04/2019

Subject: Building safety certificate for the year 1.4.2019 to 31.03.2029.

Ref:- Your letter No. DIS/ASR/CIR/12 dated 1.04.2019.

The Sub Divisional Engineer, Construction Sub Division, Ajnala vide his letter No.07 dated 04.04.2019 has reported this office that the building of Doon Internal School, Verka Byepass, in District Amritsar has been visually inspected and found the same provisionally fit for human inhabitation for the year 01.04.2019 to 31.03.2029. Your application for safety certificate will only be considered when you will fulfill all the requirement under column 14 of Proforma Part-1.

DA/Proforma 1& II


Executive Engineer,
Central Works Divn. No.2,
PWD B&R Branch Amritsar.

Endst.No.

Dated:-

Copy to the Sub Divisional Engineer, Construction Sub Division, Ajnala for information and necessary action w.r.t. his letter No. 07 dated 04.04.2019.


Executive Engineer,
Central Works Divn. No.2,
PWD B&R Branch Amritsar.

PROFORMA FOR THE SAFETY CERTIFICATE OF SCHOOL BUILDING
(PART-I)

(To be filled in by the head of school, institute)

1. Name of the School DOON INTERNATIONAL SCHOOL
2. Location VERVA BY PASS AMRITSAR
3. Plot Area 23 K 16 M OR 1,29,591 SFT
4. Covered Area of Building 72891 SQ. SFT
5. Number of Stories 3 Nos. Three story
6. Year of Construction 2018
- a) Frame Structure Frame Structure
- b) Brick masonry structure -
7. If the building has been constructed under the supervision of the qualified Engineer, the following details may be given:-
 - a) Name of Engineer with qualification KARANDEEP GROVER
 - b) Address of the Engineer Architect old Jail road
ASR
 - c) If structural drawing used in the construction, if available? Yes
 - d) Name and address of Architect with qualification KARANDEEP GROVER
SO, A, OLD Jail Road Amritsar
8. Whether the building has been constructed for the purpose of
 - a) School Yes/No
 - b) Residential purpose and used for a school Yes/No
9. Materials used for Roofs
 - a) R.C.C.Slabs Yes
 - b) R.S.Joists & Battons -
 - c) Wooden Joints and bottom -
10. Material used for Walls
 - a) Mud Mortar Yes/No
 - b) Cement Mortar Yes/No
 - c) Lime Mortar Yes/No
11. Flooring
 - a) Conglomerate Yes/No
 - b) Terrace Yes/No
 - c) Brick Paving Yes/No
12. A detailed drawing indicating the doors alongwith windows and location fitting and windows is attached.
13. FOR FIRE SAFETY
 - a) Whether the width of the staircase is 1.5 mtr. Yes/No ✓
 - b) Whether portable fire extinguisher exists Yes/No ✓
 - c) Whether School building is free from inflammable & toxic material Yes/No ✓
 - d) Whether cooking of food is done at a safe place Yes/No ✓
 - e) Whether any Thatch or combustible material has been used Yes/No ✓

14. Requirement for Fire Protection Arrangements under
NB-Part-IV
(For Building height less than 15 metre)

- | | |
|--|--------|
| a) Whether Hose Real provided | Yes/No |
| b) Whether down comer provided | Yes/No |
| c) Whether Automatic sprinkler provided | Yes/No |
| d) Whether underground static water storage tank of capacity 50000 Ltr.(if converted area exceeds 1500 sqm) | Yes/No |
| e) Whether over head tank of capacity 10000 Ltr.exists (in case of hose real) 20000 Ltr. | Yes/No |
| f) Whether one eclectic and one diesel pump of 3 kg/cum Pressure of capacity 1620 LPM, one electric pump of Capacity 180 LPK exist near underground static tank. | Yes/No |
| g) Whether a pump 3 kg/cum pressure & 450/500 LPM Exist near over head tank. | Yes/No |


Signature of the Head of School,
Institute

For Doon International School, Amritsar
Principal

PART-II

(To be filled by the SDE of PWD (B&R) Department)

- a) I have visited the above mentioned school on dated 4-3-2019 and have visually inspected it from all angles of safety and find it fit for normal use as school building.
- b) In case any addition/alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by flood, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d) This building can be safely occupied for normal use upto (indicate upto which it can be used) 31-3-2019


Sub Divisional Engineer
Construction Sub Division
P.W.D. B&R Ajnala